


UFC3/4 Self-Sealing UF Splice Kit


Installation Instructions

- 3 Wire: 14/2, 12/2, 10/2 with ground.
- 4 Wire: 14/3, 12/3, 10/3 with ground.
- Wire connector system for use with underground conductor.
- 600 volts maximum.

1. Cut the UF Cables ends properly. All conductors should be flush with outer jacket insulation.
2. Clean the cable jacket thoroughly. It must be free of dirt and contaminants.
3. Important! For 4 Wire Kits, cut off the "UFA" portion of the adapter on the cover and cap. Note: 3 wire kits are pre-cut at the factory.



4. Lubricate both UF cable ends. Slide large section of insulator assembly onto one UF cable SEALING end first. Move back onto the UF cable far enough to allow ample work space. Repeat this process with the smaller section of insulator assembly installed on the other UF cable end.



5. Strip approximately 2" off *outer jacket* insulation on both UF cable ends.
6. Strip all conductor wire insulation back approximately 9/16". Insert the bare wires into connector. Maintain continuity. Torque screws to 8 in./lbs. with a straight blade screwdriver.
7. Lubricate cap as shown. Push the cover and cap insulating sections together, the cap will slide into cover. Center the closed insulation assembly over the splice for a waterproof, re-enterable seal.