


3M™ Scotchcast™ Mine and Portable Cable Splice Kit 8096-4

Installation Instructions

1.0 Kit Contents:

- | | |
|---|--|
| 2 Funnels | 3 EPDM Rubber Cold Shrink Cold Shrink Insulator Assemblies |
| 1 Wrap-around Mold | 1 Roll Scotch® Super 33+™ Vinyl Electrical Tape |
| 2 Rubber Mold Straps | 2 Rolls Scotch® Electrical Shielding Tape 24 |
| 2 Funnel Supports | 1 3M™ Cable Cleaning Preparation Kit CC-2 |
| 3 Spacer Webs | 1 Roll Scotch® Electrical Semi-conducting Tape 13 |
| 1 Strip 3M™ Three-M-Ite™ Elek-Tro-Cut™ Abrasive Cloth, 80J Grit | 1 Roll Scotch® Linerless Rubber Splicing Tape 130C |
| 6 Size C Bags, 3M™ Scotchcast™ Flame-Retardant Compound 2131 | |

5, 8 & 15 KV Cable Types SHD-GC; MPF-GC; MPF



NOTE: On large 15kV cables, additional Scotch® Tape 130C, Scotch® Tape 13 and Scotch® Tape 24 may be required.

DANGER: BEFORE ATTEMPTING ANY CABLE REPAIRS, MAKE SURE THAT THE PROPER CABLE IS DISCONNECTED, LOCKED OUT AND SUITABLY TAGGED.



Working around energized systems may cause serious injury or death. Installation should be performed by personnel familiar with good safety practice in handling electrical equipment. De-energize and ground all electrical systems before installing product.

Technical Information:

For use on three-conductor mine and portable cables:

5 & 8kV	Type SHD-GC:	#4 AWG to 4/0 AWG
	Type MPF-GC & MPF:	1/0 AWG to 300 kcmil
15 kV	Type SHD-GC:	#2 AWG to #1 AWG
	Type MPF-GC & MPF	#2 AWG to 3/0 AWG


Mine Safety and Health Administration Acceptance:
07-KA060007-MSHA

3M™
Scotchcast™
Mine and Portable Cable Splice Kit
8096-4

78-8126-9793-2


June, 2011

2.0 Prepare Cables



- 2.1. Position cables and cut so conductor ends butt squarely.
- 2.2 Remove cable jackets for 10" (250 mm). (Figure 1)
- 2.3 **FULLY** taper jacket ends: 1" (25 mm) for jackets less than 3/16" (5 mm) thick
2" (50 mm) for jackets of 3/16" (5 mm) and thicker
- 2.4 Scuff jacket ends for 6" (150 mm) with coarse #80 abrasive strip provided. Clean dust from scuffed area. (Figure 1)
- 2.5 Remove cable fillers back to jackets.
- 2.6 Apply 2 wraps of tightly stretched Scotch® Super 33+™ Vinyl Electrical Tape around each conductor, 4" (100 mm) from end. (Figure 1)
- 2.7 Bend shielding back over the Scotch® Super 33+ Tape. *USE CARE TO EVENLY DISTRIBUTE WIRES.* (Figure 1)
- NOTE: FOR RIBBON (TAPE) SHIELDING, CUT SHIELDING OFF AT Scotch® Super 33+ TAPE AND PROCEED TO STEP 2.9.**
- 2.8 Trim shielding to 3/4" (20 mm) and overwrap with a layer of Scotch® Super 33+ Tape. (Figure 1)
- 2.9 Remove cable color-coding fabric and /or semi-conducting cloth, leaving 1/4" (6 mm) exposed beyond shielding. (Figure 1)
- 2.10 Remove insulation from ends of conductors for 1/2 connector length plus 1/4" (6 mm). *CONNECTOR LENGTH SHOULD NOT EXCEED 2 1/2" (60 mm).*
- 2.11 Clean and smooth exposed insulations using 3M™ Cable Cleaning Preparation Kit CC-2 provided. (Figure 1)
- 2.12 Pencil insulations for 3/4" (20 mm); buff *SMOOTH AND EVEN* with fine #120 abrasive from CC-2 Kit. (Figure 1)


3.0 Connect Power Conductors



- 3.1 Select one cable end and slide a cold shrink insulator assembly onto each power conductor, putting the loose core ends on first. (Figure 2)
- 3.2 Phase match conductors to appropriate color codes.
- 3.3 Join power conductors with proper connectors and appropriate crimping tool and die. *MAKE CERTAIN CONDUCTORS BUTT INDENTS IN CENTER OF CONNECTORS.*

NOTE: GROUND WIRES AND GROUND CHECK WILL BE JOINED LATER.

Figure 3




- 3.4 Fill connector indents with Scotch® Electrical Semi-Conducting Tape 13; smoothly apply 2 half-lapped layers, highly elongated over exposed conductor and connector area, *OVERLAPPING 1/16" (2 mm) ONTO INSULATION PENCILS*. (Figure 3)

4.0 Apply Primary Insulation


NOTE: On large 15 kV cables, additional Scotch® Linerless Rubber Splicing Tape 130C, Scotch® Tape 13 and Scotch® Electrical Shielding Tapes 24 may be needed.

Figure 4



- 4.1 Smoothly fill in connector area with half-lapped, highly elongated Scotch® Tape 130C; *BUILD UP TO DIAMETER OF CABLE INSULATION*, overlapping 1/16" (2 mm) beyond pencils. (Figure 4)


Figure 5



- 4.2 Slide cold shrink insulator assembly over taped connection. As the core is removed, the rubber tube will elongate approximately 1/4". Position insulator so tube is centered over connection when core is removed.
- 4.3 Remove cores by UNWINDING COUNTERCLOCKWISE. (Figure 5)

NOTE: An occasional tug of the strand while unwinding will aid in removal of core.

Figure 6



- 4.4 Apply highly elongated Scotch® Linerless Rubber Splicing Tape 130C to cable insulation at ends of cold shrink insulators, forming tapers to insulators. Extend tapers from cable color-coding fabric and/or semi-conducting cloth to 1/16" (2 mm) onto insulators. (Figure 6)


FOR 15kV ONLY: Extend tapers from cable color-coding fabric and/or semi-conducting cloth to insulators. Wrap an additional 2 half-lapped layers of Scotch® Tape 130C over cold shrink insulators.

- 4.5 Wrap 1 half-wrapped layer of Scotch® Electrical Semi-Conducting Tape 13 over previously applied Scotch® Tape 130C and cold shrink insulators extending 1/2" (12 mm) onto exposed cable metallic shielding. (Main illustration – front page)
- 4.6 Wrap 1 half-lapped layer of Scotch® Electrical Shielding Tape 24 over the semi-conducting tape, extending 1/2" (12 mm) onto exposed cable metallic shielding. Secure ends with 2 wraps of tightly applied Scotch® Super 33+™ Vinyl Electrical Tape. (Main illustration – front page)


5.0 Connect Ground Wires

- 5.1 Join ground wires with proper connectors and appropriate crimping tool and die. Half-lap or overwrap entire length of ground wires with Scotch® Super 33+ Tape.
- 5.2 *GROUND CHECK* (if present): remove conductor insulation for 1/2 connector length. Join wires with proper connector. Insulate connection with 2 half-lapped layers of Scotch® Super 33+ Tape, extending 1" (25 mm) onto conductor insulations. Half-lap or overwrap remaining exposed ground check insulation with Scotch® Super 33+ Tape.
- 5.3 Bundle all conductors, grounds, and ground check (if present) by overwrapping entire length with 2 half-lapped layers of Scotch® Super 33+ Tape, extending 1/4" (6 mm) onto jacket taper at each end.

6.0 Install Spacer Web



- 6.1 Wrap *INVERTED* Scotch® Super 33+ Tape (adhesive side out) around bundled conductors at 5 1/2" (140 mm) spacing, as shown in Figure 7.
- 6.2 Wrap on spacer web over inverted Scotch® Super 33+ Tape to form collars; build *EQUAL* diameters to 1 layer greater than repair or cable diameter, whichever is larger. (Figure 7)



- 6.3 Split ends of spacer web and press into sides of collars. (Figure 8)


7.0 Install Mold

- 7.1 Inspect Mold: On previously used mold, make certain vent slits are clear of resin.



- 7.2 With cable straight, center mold over repair area with vent slits on top (printing on mold should be readable). Wrap snugly around, tucking one edge under. (Figure 9)


NOTE: TUCKED EDGE MUST BE STRAIGHT TO FORM A SEAL.



- 7.3 On small cables, where mold overlaps mold fill-holes, reduce mold width by folding, then cutting on appropriate score marks. (Figure 10)
- 7.4 Reposition mold according to Step 7.2.

NOTE: IF NECESSARY, SLIGHTLY ADJUST MOLD POSITION SO SPACER WEB COLLARS ARE NOT BLOCKING MOLD FILL-HOLES.


Caution: Mold must not overlap fill-holes.



- 7.5 Position Funnel Supports over mold holes and secure tightly with Mold Straps. (Figure 11)

NOTE: MOLD, FUNNEL SUPPORTS AND MOLD STRAPS MAY BE MOVED AROUND AT THIS TIME, TO ADJUST FOR FINAL POSITION.

Figure 12



- 7.6 Bundle mold's notched ends evenly around cable, maintaining cable centering. Starting 1/2" (12 mm) on cable jacket, apply 1 half-lapped layer of Scotch® Super 33+™ Vinyl Electrical Tape over notches. (Figure 12)


NOTE: *TENSION Scotch® Super 33+ TAPE ONLY ENOUGH TO CONFORM TO MOLD.*

- 7.7 Install funnels into Funnel Support holes. (Figure 11)

8.0 Pour Compound


- 8.1 Premix BLACK side of 3M™ Scotchcast™ Flame Retardant-Compound 2131 pouch by squeezing to a smooth consistency and uniform color.

Figure 13



- 8.2 Firmly grasp each flat side of the closed mixing pouch near the center barrier; at the same time, pull sides of barrier apart and roll sides of thumbs through barrier. Break the barrier all the way across to the side seals. (Figure 13)

Figure 14



- 8.3 Alternately squeeze ends of pouch forcing compound rapidly back and forth, strip compound from corners of pouch between fingers. Mix until color is completely uniform – 30 to 40 VIGOROUS SQUEEZES. *DO NOT EXCEED 1 MINUTE.* (Figure 14)
- 8.4 Clip off a corner of pouch and immediately pour into funnels, alternating back and forth between them.
- 8.5 Fill mold until compound fills funnels to 1/2 full.
- 8.6 Allow compound to cure.
- 8.7 Check compound in Funnels for curing.


NOTE: *REPAIR MAY BE DE-MOLDED WHEN COMPOUND IS NO LONGER TACKY.*

Typical Cure Time: 16 – 24 hrs. @ 70°F (21°C)
24 – 30 hrs. @ 50°F (10°C)
36 hrs. @ 32°F (0°C)

Typical De-mold Time: 1.5 hrs. @ 70°F (21°C)
4 hrs. @ 50°F (10°C)
6 – 8 hrs. @ 32°F (0°C)

NOTE: Values are typical, not to be considered minimum or maximum. Always confirm based on tack and hardness of compound.

9.0 De-mold



- 9.1 Remove funnels by twisting and lifting, breaking off from compound. (Figure 15)
- 9.2 Remove Mold Straps and Funnel Supports. (Figure 15)
- 9.3 Carefully cut off spout compound protrusions from repair, using a knife. (Figure 15)
- 9.4 Remove Scotch® Super 33+™ Vinyl Electrical Tape from mold ends.
- 9.5 Remove mold from cable repair, working from ends toward center.

3M, Scotch, Scotchcast, Super 33+, Three-M-Ite and Elek-Tro-Cut are trademarks of 3M Company.

Important Notice:

All statements, technical information, and recommendations related to 3M's products are based on information believed to be reliable, but the accuracy or completeness is not guaranteed. Before using this product, you must evaluate it and determine if it is suitable for your intended application. You assume all risks and liability associated with such use. Any statements related to the product, which are not contained in 3M's current publications, or any contrary statements contained on your purchase order, shall have no force or effect unless expressly agreed upon, in writing, by an authorized officer of 3M.

Warranty; Limited Remedy; Limited Liability:

This product will be free from defects in material and manufacture at the time of purchase. 3M MAKES NO OTHER WARRANTIES INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. If this product is defective within the warranty period stated above, your exclusive remedy shall be, at 3M's option, to replace or repair the 3M product or refund the purchase price of the 3M product. Except where prohibited by law, 3M will not be liable for any indirect, special, incidental or consequential loss or damage arising from this 3M product, regardless of the legal theory asserted.



Electrical Markets Division
6801 River Place Blvd.
Austin, TX 78726-9000
800.245.3573
Fax 800.245.0329
www.3M.com/electrical

Please Recycle. Printed in USA.
© 3M 2011 All Rights Reserved.
78-8126-9793-2 A