

HUBBELL FIRE-RATED ABANDONMENT PLATE
Cat. No. AP-22

This cover provides an approved method of abandoning Hubbell Poke-Through Catalog No. PT-27 with an above floor service fitting, and maintaining the fire rating of the installation.

NOTE: Abandoning an active Poke-Through must be done by a qualified electrician.

Instructions for Abandoning

1. Disconnect power to Poke-Through junction box below the floor and disconnect telephone/data service, and above floor fitting.
2. From floor below, disconnect wires inside poke-through junction box and also remove telephone/data wires. Close junction box again.
3. Install Plate AP-22 using two (2) pan head screws removed in step 1.



Wiring Device Division