





CCB02

Ref.	Pic.	Qty.
A		2





Unmounting



Remove screw and washer

Mounting



Torque
15-20 Nm

A